

# Inspection Photos

10/18/2017

Operator: WESTERN OPERATING COMPANY -  
95620

Location ID: 312292

Inspection Doc. Number: 682502714  
Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312292



**Photo 1:** Photo taken from the east side of the well. Photo shows sign has been placed at well per the CA



**Photo 2:** Photo taken from the west end of the well. Previous inspection required operator to properly store or remove unneeded equipment.





**Photo 3:** Photo taken from the northeast corner of the pit. Photo shows erosion degradation on the pit.



**Photo 4:** Photo taken from the northeast corner of the pit. Photo shows erosion degradation on the pit.



Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 5:** Photo shows skim pit remains.



**Photo 6:** Photo taken from the south end of the location, facing northeast. Inspection #675103909 required operator to install temporary stormwater and sediment control BMPs until reclamation activities have been conducted, and more permanent stabilization controls can be implemented. Photo shows no controls have been implemented.



Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 7:** Photo taken from the south end of the location, facing west. See comments under photo 6. Photo shows no controls have been implemented.



**Photo 8:** Photo taken from the north end of the location, facing south. See comments under photo 6. Photo shows no controls have been implemented.



Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 9:** Photo taken from the southeast end of the pit, facing west. See comments under photo 6. Photo shows no controls have been implemented.



**Photo 10:** Photo taken from the southwest end of the pit, facing north. See comments under photo 6. Photo shows no controls have been implemented.



Inspection Photos  
Operator: WESTERN OPERATING COMPANY - 95620  
Location ID: 312292



**Photo 11:** Photo taken from the southwest end of the pit, facing northwest. See comments under photo 6. Photo shows no controls have been implemented.



**Photo 12:** Photo taken from the location, to the west of the battery. See comments under photo 6. Photo shows no controls have been implemented.