

Inspection Photos
Location Name: Furr F3 Pad
Location ID: 335021



Photo 1. Tank and sand trap have been removed from location. Corrective actions for containment and sign have been met.