

TR 11-17-597 pad  
Api # 05-045-14224  
Inspection # 689700584



Well photo

TR 11-17-597 pad  
Api # 05-045-14224  
Inspection # 689700584



**Gap in netting at south east corner of pit.**

TR 11-17-597 pad  
Api # 05-045-14224  
Inspection # 689700584



**Gap in netting at north end of pit by the Condensate tank.**

TR 11-17-597 pad  
Api # 05-045-14224  
Inspection # 689700584



**Hydrocarbons observed on pit**

TR 11-17-597 pad  
Api # 05-045-14224  
Inspection # 689700584



Unused chemical empty container next to separators.

Unused chemical empty container next to separators.