

TR 33-3-597 pad  
Api # 05-045-12639  
Inspection # 689700586



**Well photo**

TR 33-3-597 pad  
Api # 05-045-12639  
Inspection # 689700586



Unused piping sitting by wells,