

Inspection Photos
Well Name: FEDERAL 10-90-32
Location ID: 324459



Photo 1. Vegetation and vegetation debris on berm and in tank containment.



Photo 2. Vegetation and vegetation debris on berm and in tank containment. NFPA diamond starting to peel.