

Inspection Photos
Well Name: FEDERAL 10-90-31
Location ID: 324458



Photo 1. Vegetation and vegetation debris on berm and in tank containment.



Photo 2. Stained tanks.

Inspection Photos
Well Name: FEDERAL 10-90-31
Location ID: 324458



Photo 3. Update NFPA diamond on tanks.



Photo 4. Trash near gas meter run.