

Inspection Photos
Well Name: COW SKULL 11-89-18 1
Location ID: 414132



Photo 1. Capacity is faded on tank.



Photo 2. Update NFPA diamond for Fire Hazard or provide documentation for 0 rating. Capacity faded on tank.