

# Final Reclamation Inspection

November 2, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP - # 47120

API: 05-123-10973

Weld County, CO

NWSE Section 13 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 1.** COGCC GISOnline database aerial imagery from 2013 illustrating the well and battery location during operations.

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 2.** COGCC GISOnline database aerial imagery from 2015 illustrating the well and battery location. The well location appears to meet Rule 1004 standards but the tank battery location does not meet Rule 1004 standards. Refer to the following photos for more detail.

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 3.** Photo taken from the approximate center of the battery location, facing South. Disturbance areas are not reflective of reference areas. Location mainly consists of weedy, annual vegetation and appears gravel material may have been left at location.

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 4.** Photo taken from the western battery location, facing South. See comments under Photo 3.



**Photo 5.** Photo taken from the approximate center of the battery location, facing Southeast. See comments under Photo 3.

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 6.** Photo taken from the approximate center of the battery location, facing East. See comments under Photo 3.



**Photo 7.** Photo taken from the approximate center of the well location, facing East. The well location appears to meet Rule 1004 standards.

Inspection Photos  
Location Name: RIX #1  
API: 05-123-10973



**Photo 8.** Reference photo taken south of the battery location, facing South.