

Final Reclamation Inspection

December 12, 2017

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06159

Larimer County, CO

SWNW Section 31 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 1. Photo taken on May 26, 2017 from the well location, facing South. Gravel has not been removed from location. Operator has failed to perform reclamation activities per Rule 1004.a.



Photo 2. Photo taken on December 12, 2017 from the well location, facing South. Operator has failed to perform reclamation activities per Rule 1004.a. and has failed to respond to the previous corrective action inspection.

Inspection Photos
Location Name: PROCTOR-SKAER #1-A
API: 05-069-06159



Photo 3. Photo taken on May 26, 2017 from a portion of the access road, facing West. Operator has failed to perform reclamation activities per Rule 1004.a. Along the access road.



Photo 4. Photo taken on December 12, 2017 from a portion of the access road, facing West. Operator has failed to perform reclamation activities per Rule 1004.a. and has failed to respond to the previous corrective action inspection.