

Inspection Photos
Location Name: Bruton 30-03 Pad
Location ID: 451421



Photo 1. No signs at wellheads. Original corrective action and date are in place.



Photo 2. Tank has been moved back on location to meet corrective action..