

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2017

Submitted Date:

01/07/2018

Document Number:

680102531**FIELD INSPECTION FORM**

Loc ID 335851	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>																																																																																																											
Contact Information: <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td>lrider@caerusoilandgas.com</td> <td></td> </tr> <tr> <td></td> <td></td> <td>cogcc.inspections@encana.com</td> <td></td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment			lrider@caerusoilandgas.com				cogcc.inspections@encana.com																																																																																												
Contact Name	Phone	Email	Comment																																																																																																								
		lrider@caerusoilandgas.com																																																																																																									
		cogcc.inspections@encana.com																																																																																																									
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>285043</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12353</td><td>N PARACHUTE WF04B O10A 596</td><td>RI</td></tr> <tr><td>285044</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12354</td><td>N PARACHUTE WF03B O10A 596</td><td>RI</td></tr> <tr><td>285045</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12355</td><td>N PARACHUTE MF04D O10A 596</td><td>RI</td></tr> <tr><td>285046</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12356</td><td>N PARACHUTE WF06B O10A 596</td><td>RI</td></tr> <tr><td>285047</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12357</td><td>N PARACHUTE WF12D O10A 596</td><td>RI</td></tr> <tr><td>285062</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12368</td><td>N PARACHUTE WF12B O10A 596</td><td>RI</td></tr> <tr><td>285107</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12375</td><td>N PARACHUTE WF08D O10A 596</td><td>RI</td></tr> <tr><td>285108</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12374</td><td>N PARACHUTE WF09D O10A 596</td><td>RI</td></tr> <tr><td>285109</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12373</td><td>N PARACHUTE WF13B O10A 596</td><td>RI</td></tr> <tr><td>285110</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12372</td><td>N PARACHUTE WF13D O10A 596</td><td>RI</td></tr> <tr><td>285111</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-12371</td><td>N PARACHUTE WF14B O10A 596</td><td>RI</td></tr> <tr><td>285112</td><td>WELL</td><td>AL</td><td>02/04/2013</td><td>LO</td><td>045-12370</td><td>N PARACHUTE WF16D O10A 596</td><td>RI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	285043	WELL	AL	10/13/2011	LO	045-12353	N PARACHUTE WF04B O10A 596	RI	285044	WELL	AL	10/13/2011	LO	045-12354	N PARACHUTE WF03B O10A 596	RI	285045	WELL	AL	10/13/2011	LO	045-12355	N PARACHUTE MF04D O10A 596	RI	285046	WELL	AL	10/13/2011	LO	045-12356	N PARACHUTE WF06B O10A 596	RI	285047	WELL	AL	10/13/2011	LO	045-12357	N PARACHUTE WF12D O10A 596	RI	285062	WELL	AL	10/13/2011	LO	045-12368	N PARACHUTE WF12B O10A 596	RI	285107	WELL	AL	10/13/2011	LO	045-12375	N PARACHUTE WF08D O10A 596	RI	285108	WELL	AL	10/13/2011	LO	045-12374	N PARACHUTE WF09D O10A 596	RI	285109	WELL	AL	10/13/2011	LO	045-12373	N PARACHUTE WF13B O10A 596	RI	285110	WELL	AL	10/13/2011	LO	045-12372	N PARACHUTE WF13D O10A 596	RI	285111	WELL	AL	10/13/2011	LO	045-12371	N PARACHUTE WF14B O10A 596	RI	285112	WELL	AL	02/04/2013	LO	045-12370	N PARACHUTE WF16D O10A 596	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																				
285043	WELL	AL	10/13/2011	LO	045-12353	N PARACHUTE WF04B O10A 596	RI																																																																																																				
285044	WELL	AL	10/13/2011	LO	045-12354	N PARACHUTE WF03B O10A 596	RI																																																																																																				
285045	WELL	AL	10/13/2011	LO	045-12355	N PARACHUTE MF04D O10A 596	RI																																																																																																				
285046	WELL	AL	10/13/2011	LO	045-12356	N PARACHUTE WF06B O10A 596	RI																																																																																																				
285047	WELL	AL	10/13/2011	LO	045-12357	N PARACHUTE WF12D O10A 596	RI																																																																																																				
285062	WELL	AL	10/13/2011	LO	045-12368	N PARACHUTE WF12B O10A 596	RI																																																																																																				
285107	WELL	AL	10/13/2011	LO	045-12375	N PARACHUTE WF08D O10A 596	RI																																																																																																				
285108	WELL	AL	10/13/2011	LO	045-12374	N PARACHUTE WF09D O10A 596	RI																																																																																																				
285109	WELL	AL	10/13/2011	LO	045-12373	N PARACHUTE WF13B O10A 596	RI																																																																																																				
285110	WELL	AL	10/13/2011	LO	045-12372	N PARACHUTE WF13D O10A 596	RI																																																																																																				
285111	WELL	AL	10/13/2011	LO	045-12371	N PARACHUTE WF14B O10A 596	RI																																																																																																				
285112	WELL	AL	02/04/2013	LO	045-12370	N PARACHUTE WF16D O10A 596	RI																																																																																																				

Contact Name	Phone	Email	Comment
		lrider@caerusoilandgas.com	
		cogcc.inspections@encana.com	

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285043	WELL	AL	10/13/2011	LO	045-12353	N PARACHUTE WF04B O10A 596	RI
285044	WELL	AL	10/13/2011	LO	045-12354	N PARACHUTE WF03B O10A 596	RI
285045	WELL	AL	10/13/2011	LO	045-12355	N PARACHUTE MF04D O10A 596	RI
285046	WELL	AL	10/13/2011	LO	045-12356	N PARACHUTE WF06B O10A 596	RI
285047	WELL	AL	10/13/2011	LO	045-12357	N PARACHUTE WF12D O10A 596	RI
285062	WELL	AL	10/13/2011	LO	045-12368	N PARACHUTE WF12B O10A 596	RI
285107	WELL	AL	10/13/2011	LO	045-12375	N PARACHUTE WF08D O10A 596	RI
285108	WELL	AL	10/13/2011	LO	045-12374	N PARACHUTE WF09D O10A 596	RI
285109	WELL	AL	10/13/2011	LO	045-12373	N PARACHUTE WF13B O10A 596	RI
285110	WELL	AL	10/13/2011	LO	045-12372	N PARACHUTE WF13D O10A 596	RI
285111	WELL	AL	10/13/2011	LO	045-12371	N PARACHUTE WF14B O10A 596	RI
285112	WELL	AL	02/04/2013	LO	045-12370	N PARACHUTE WF16D O10A 596	RI

General Comment:

This is an Abandoned Location Inspection for for Twelve Wells, listed in Related Facilities, above; APDs First Approved in 2006; Permits Abandoned in 2011 & 2012.

Inspected Facilities				
Facility ID: <u>285043</u>	Type: <u>WELL</u>	API Number: <u>045-12353</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285044</u>	Type: <u>WELL</u>	API Number: <u>045-12354</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285045</u>	Type: <u>WELL</u>	API Number: <u>045-12355</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285046</u>	Type: <u>WELL</u>	API Number: <u>045-12356</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285047</u>	Type: <u>WELL</u>	API Number: <u>045-12357</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285062</u>	Type: <u>WELL</u>	API Number: <u>045-12368</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285107</u>	Type: <u>WELL</u>	API Number: <u>045-12375</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285108</u>	Type: <u>WELL</u>	API Number: <u>045-12374</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285109</u>	Type: <u>WELL</u>	API Number: <u>045-12373</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285110</u>	Type: <u>WELL</u>	API Number: <u>045-12372</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285111</u>	Type: <u>WELL</u>	API Number: <u>045-12371</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>285112</u>	Type: <u>WELL</u>	API Number: <u>045-12370</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass

Compaction alleviation Pass Dust and erosion control Pass

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **APDs have not been drilled, No Wells were observed. Location was constructed and has been partially Reclaimed. Graveled Access Road & Turn-around area have Not been Reclaimed. Snow cover prevented detailed assessment of Vegetation.**

Corrective Action:	Perform Final Reclamation of Access Road & Turn around area per COGCC 1004 Rules; Reclamation Activities to be complete by June 1, 2018	Date	06/01/2018
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401505474	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4343068
680102555	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4343063