Inspector Name: CONKLIN, CURTIS

FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Facility Name

Nichols 0994-13-20E

Inspection Date:

02/06/2018
Submitted Date:

02/07/2018
Document Number:

689400946

Insp Status

DG

FIELD INSPECTION FORM

Loc ID	Inspector Name:		On-Site Inspection		Status Summary:		
450791	CONKLIN, CURTIS		2A Doc Num:		THIS IS A FOLLOW UP INSPECTION		
Operator Information:					FOLLOW UP INSPECTION REQUIRED		
OGCC Opera	itor Number: 10	0433			NO FOLLOW UP INSPECTION REQUIRED		
Name of Operator: LARAMIE ENERGY LLC					Findings:		
Address: 1401 SEVENTEENTH STREET #1400					4 Number of Comments		
/ taarooo: 110	31 OE VEIVI EEIVIII V	311KEE1 // 11			0 Number of Corrective Actions		
City:	DENVER S	tate: CO	Zip: _	80202	Corrective Action Response Requested		
Contact Info	rmation:						
Contact Name Phone		Phone	Email		Comment		
Laramie Energy LLC			cogccnoti energy.co	fications@laram m	ie- All Inspections		
Inspected Facilities:							

General Comment:

Type

WELL

Status

DG

Status Date

02/03/2018

Facility ID

450787

This is a routine drilling inspection, any corrective actions not addressed from previous inspections are still applicable.

Well Class

API Num

077-10403

Inspector Name: CONKLIN, CURTIS **Location** Overall Good: X Signs/Marker: Type DRILLING/RECOMP Comment: Corrective Action: Date: Emergency Contact Number: Comment: Corrective Action: Date: Overall Good: X Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: CONKLIN, CURTIS									
Inspected Facilities									
Facility ID: 450787	Type:	WELL	API Numb	oer: 077-1	0403	Status:	DG	Insp. Status:	DG
			We	ell Drilling					
Rig: Rig Name:	H&P 290	Pus	her/Rig Ma	anager: Roge	r Foster				
Permit Posted:	Yes		Acces	s Sign: Yes					
Well Control Equipn	nent:								
Pipe Ram:	YES_	Blind Ram:	YES	Hydril Type:	YES				
Pressure Test BOP:	Pass	Test Pressure PSI:	5000	Safety Plan					
<u>Drill Fluids</u> <u>Management:</u>					YES	_			
Lined Pit:		Unlined Pit:		Clos	ed Loop:	YES	Semi	i-Closed Loop:	
Multi-Well:	YES	Disposal Location	: On Loca	tion					
<u>Comment:</u>	BOP Test of been received	n 2/2/18. Running p	oduction c	asing at time	of inspect	ion. Notifica	ations have		
Corrective Action:								Date:	

Inspector Name: CONKLIN, CURTIS

Reclamation - Storm Water - Pit						
1.100/amarion 0.101m Water 1 It						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Covering Materials	Pass	
Comment: Could not do complete stormwater inspection due to snow cover.						
Corrective Action: Date:					Date:	
Pits: X NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
689400947	Nichols 0994-13-20E Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4372210

Date Run: 2/7/2018 Doc [#689400946]