Inspector Name: CONKLIN, CURTIS

FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Facility Name

Nichols 0994-13-20E

Inspection Date:

02/06/2018

Submitted Date:

02/07/2018

Document Number:

689400946

Insp Status

DG

FIELD INSPECTION FORM

Loc ID	: ID Inspector Name:		e Inspection	Status Summary:		
450791	CONKLIN, CURT	IS :	2A Doc Num:	THIS IS A FOLLOW UP INSPECTION		
Operator In	nformation:		FOLLOW UP INSPECTION REQUIRED			
OGCC Ope	erator Number:10	0433	NO FOLLOW UP INSPECTION REQUIRED			
Name of Or	perator: LARAMIE ENE	ERGY LLC	Findings:			
Address: 1401 SEVENTEENTH STREET #1400				4 Number of Comments		
City:	DENVER S	tate: CO	Zip: 80202	0 Number of Corrective Actions Corrective Action Response Requested		
Contact Inf	formation:			<u> </u>		
Contact Name Pr		Phone	Email	Comment		
Laramie Energy LLC			cogccnotification energy.com	ns@laramie- All Inspections		
Inspected Facilities:						

General Comment:

Type

WELL

Status

DG

Status Date

02/03/2018

Facility ID

450787

This is a routine drilling inspection, any corrective actions not addressed from previous inspections are still applicable.

Well Class

API Num

077-10403

Inspector Name: CONKLIN, CURTIS **Location** Overall Good: X Signs/Marker: Type DRILLING/RECOMP Comment: Corrective Action: Date: Emergency Contact Number: Comment: Corrective Action: Date: Overall Good: X Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: CONKLIN, CURTIS									
Inspected Facilities									
Facility ID: 450787	Type:	WELL	API Numb	oer: 077-1	0403	Status:	DG	Insp. Status:	DG
			We	ell Drilling					
Rig: Rig Name:	H&P 290	Pus	her/Rig Ma	anager: Roge	r Foster				
Permit Posted:	Yes		Acces	s Sign: Yes					
Well Control Equipn	nent:								
Pipe Ram:	YES_	Blind Ram:	YES	Hydril Type:	YES				
Pressure Test BOP:	Pass	Test Pressure PSI:	5000	Safety Plan					
<u>Drill Fluids</u> <u>Management:</u>					YES	_			
Lined Pit:		Unlined Pit:		Clos	ed Loop:	YES	Semi	i-Closed Loop:	
Multi-Well:	YES	Disposal Location	: On Loca	tion					
Comment: BOP Test on 2/2/18. Running production casing at time of inspection. Notifications have been received.									
Corrective Action:								Date:	

Inspector Name: CONKLIN, CURTIS

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs			Chemical BMP Maintenance	Comment		
				Material Handling And Spill Prevention	Pass	
				Covering Materials	Pass	
Comment: Could not do complete stormwater inspection due to snow cover.						
Corrective Action:				Date:		
Pits: NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

_		
Document Num	Description	URL
689400947	Nichols 0994-13-20E Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4372210

Date Run: 2/7/2018 Doc [#689400946]