

B&V 24B-07-07-95
Api# 05-045-22705
Inspection # 689700993



Location sign.

B&V 24B-07-07-95
Api# 05-045-22705
Inspection # 689700993



Location photo

B&V 24B-07-07-95
Api# 05-045-22705
Inspection # 689700993



Tank battery

B&V 24B-07-07-95
Api# 05-045-22705
Inspection # 689700993



Label contents scribbled out and wrong volumes.

B&V 24B-07-07-95
Api# 05-045-22705
Inspection # 689700993



Unused 1-1" riser on east side of tank battery is unmarked and not locked out tagged out.