

Inspection Photos

API#045-07463

Operator: Encana

Inspection Number: 680102670

Inspection Date: 2/6/2018



Photo#1:
Over view of Location to North from Access Road Entry into Location.

February 6, 2018



Photo#2:
Over view of Location to Southeast.

February 6, 2018



Photo#3:
Close up view of ground Conditions in central Pad area.

February 6, 2018



Photo#4:

View along West side of Location to South where Vegetation is better established. Piece of Debris in foreground

February 6, 2018



Photo#5:

View along Access Road running West into Location.

February 6, 2018