Inspector Na	ame: Welsh, Brian									
FORM		ļ	State of Col	orado				D N R		ion Date:
INSP	Oil a	and Gas	s Conservat	ion Co	mmiss	ion				03/07/2018
Rev X/15	1		Street, Suite 801, De							ted Date:
		Phone:	(303) 894-2100 Fax	: (303) 894-	2109					03/07/2018
		FIELI			ORM					ent Number: 679904101
Loc ID	Inspector Nar	ne:	On-Site I	nspectior	n 🔲		<u>Statu</u>	is Summary:		
336762	Welsh, Brian		2A	Doc Nu	n:		Т	HIS IS A FOLLOW UP	INSPEC	TION
Operator In	formation:						F	OLLOW UP INSPECTI	ON REQ	UIRED
OGCC Ope	rator Number:	10112						IO FOLLOW UP INSPE	CTION F	REQUIRED
Name of Op	erator: FOUNDAT	TION ENE	RGY MANAGE	MENT LL	.C		<u>Findi</u>	ings:		
Address: 5	057 KELLER SPR		STE 650				5	Number of Commen	ts	
_							0	Number of Correctiv	e Actions	5
City:	ADDISON	State:	TX	Zip:	7500	1	C	orrective Action Response	Requeste	ed
Contact Inf	ormation:									
Contact Na	ame	Pho	ne	Email				Comment		
Grant, Rac	hael	918- 212	-585-1650 ext	regulate com	ory@fou	ndationen	nergy.			
Inspected F	acilities:									
Facility ID	Туре	Status	Status Date	Wel	Class	API Num	ı	Facility Name		Insp Status
279020	WELL	PR	06/01/2015	GW		125-093	82	RENZELMAN 9-22		PR
General Co	mment:									
Routine Ins	spection									

Inspector Name: Welsh, Brian

		<u> </u>	Location			
Lease Road:						
Туре	Access					
comment:	Trail through pasture					
Corrective ActionL				Date:		
Overall Good: 🔀	1					
Signs/Marker:						
Туре	WELLHEAD					
Comment:	Lease sign by wellhead. U	Jpdate to current of	operator			
Corrective Action:				Date	:	
Emergency Contact I	Number:					
Comment:						
Corrective Action		Date:				
Overall Good: 🔀						
<u>Spills:</u>						
Туре	Area	Volume		_		
In Containment: I	No		1			
Comment:						
Multilple Spills	and Palaasas?					
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
Flaring:						
Туре						
Comment:						
Corrective Action:				Date:		

								Inspe	ected	Faciliti	<u>es</u>							
Facility ID:	27902	0	Type:		WELL		API	Numb	er:	125-09	9382	Statu	s:	PR	Ins	p. Status:	P	R
Producing Well Comment: Producing. Casing production. Central meter run for (Renzelman 4-22, 8-22, 9-22, 10-22, 12-23, 15-22, 16-22 & Noble DP) 2350' SW @ Renzelman 4-22																		
C	omment:	Produ 9-22,	icing. (10-22,	Casing 12-23	produ , 15-2	iction. 2, 16-2	Centra 22 & N	al mete oble D	er run P) 23	for (Rer 50' SW	nzelman 4 @ Renze	4-22, 8-2 elman 4-3	2, 22					
Correctiv															Da	te:		

Reclamation - Storm Water - Pit

BMP Maintenance	Lease Road Erosic BMPs	on Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment						
Pass	Other	Pass									
Access and lo	Access and location are grassed over										
	CATION OF PIT										
	https://cogcc.state	e.co.us/weblink/) ar	d search by doc	ument number:							
Description	URL	URL									
NSPECTION SUBMITTED	<u>http:/</u>	/ogccweblink.state.co	DocumentId=4396556								
	Maintenance Pass Access and loc SURFACE INDIC Ents GCC Images (Description NSPECTION	Maintenance BMPs Pass Other Access and location are grassed of SURFACE INDICATION OF PIT ents GCC Images (https://cogcc.state Description URL NSPECTION http://	Maintenance BMPs Maintenance Pass Other Pass Access and location are grassed over Ents SURFACE INDICATION OF PIT ents GCC Images (https://cogcc.state.co.us/weblink/) and Description URL NSPECTION	Maintenance BMPs Maintenance Pass Other Pass Access and location are grassed over Access and location are grassed over SURFACE INDICATION OF PIT ents GCC Images (https://cogcc.state.co.us/weblink/) and search by doct Description URL NSPECTION http://ogccweblink.state.co.us/DownloadDoct	Maintenance BMPs Maintenance Maintenance Pass Other Pass Image: Comparison of the compariso						