Inspector Na	ame: Welsh, Brian									
FORM INSP Rev X/15	Oil a 1	Inspection Date: <u>03/07/2018</u> Submitted Date: <u>03/07/2018</u> Document Number: <u>679904106</u>								
Loc ID 304142										
Operator In	formation:		OLLOW UP INSPECTION REQUIRED							
OGCC Ope	rator Number:	O FOLLOW UP INSPECTION REQUIRED								
Name of Op	erator: FOUNDAT	ION ENE	<u>Findi</u>	ings:						
Addroso: E			STE 650				5	Number of Commen	its	
Address: 5057 KELLER SPRINGS RD STE 650									e Actions	5
City:	ADDISON	State:	TX	Zip:	75001	1	С С	orrective Action Response	Requeste	d
Contact Inf	ormation:									
Contact Name Phone Email								Comment		
Grant, Rachael 918-585-1650 ext regulatory@foundationenergy. 212 com										
Inspected F	acilities:									
Facility ID	Туре	Status	Status Date		Class	API Num		Facility Name		Insp Status
254118	WELL	PR	06/01/2015	GW		125-0799	96	RENZELMAN 8-22		PR
General Co										
Routine In:	spection									

Inspector Name: Welsh, Brian

		<u> </u>	Location								
Lease Road:											
Туре	Access										
comment:	Access wellhead through										
Corrective ActionL	Date										
Overall Good: 🔀											
Signs/Marker:	gns/Marker:										
Туре	WELLHEAD										
Comment:	Lease sign at wellhead. Update to current operator										
Corrective Action:				Date	:						
Emergency Contact I	Number:			1							
Comment:	:										
Corrective Action	:			Date:	Date:						
Overall Good: 🔀											
Spills:											
Туре	Area	Volume		_							
In Containment: I											
Comment:											
Multilple Spills	and Poloasos?										
Venting:											
Yes/No	NO										
Comment:											
Corrective Action:				Date:							
Flaring:				I							
Туре											
Comment:											
Corrective Action:				Date:							

Inspected Facilities																	
Facility ID:	25411	8	Type:		NELL		API N	lumber	:	125-079	96	Status	:PF	٤	Insp. S	tatus: _	PR
										Well							
С	omment	Produ 9-22,	ucing. C 10-22,	Casing 12-23	produc , 15-22	ction. C 2, 16-22	Central 2 & No	meter ble DP	run fo ) 800'	r (Renze NE @ F	elman 4 <sup>.</sup> Renzelm	-22, 8-22 Ian 4-22	,				
Correctiv															Date:		

Inspector Name: Welsh, Brian

	Reclamation - Storm Water - Pit											
Storm Water:												
Loc Erosion BMPs	BMP Maintenance	Lease Road E BMPs	Erosion	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment					
Other	Pass											
Commen	t: Location is gra	ssed over and	in creek bo	ottom	•							
Corrective Actio	n:											
Pits: 🕅 NC	SURFACE INDI	CATION OF PI	IT									
Attached Docur	<u>ments</u>											
You can go to Co	OGCC Images (	https://cogcc.	.state.co.u	<u>ıs/weblink/</u> ) an	d search by doc	ument number:						
Document Num			URL									
401566889 INSPECTION <u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4396561</u> SUBMITTED												