

Inspection Photos  
Location Name: Titanium 26-10-7HI & 2  
API: 05-057-06094



**Photo 1. Overview of location taken at entrance facing west.**

Inspection Photos  
Location Name: Titanium 26-10-7HI & 2  
API: 05-057-06094



**Photo 2. No capacity on crude oil tanks.**



**Photo 3. No capacity on produced water tank.**