

Inspection Photos

Loc# 324472

Operator: SG Interests

Inspection Number: 680102873

Inspection Date: 4/17/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

April 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SG Interests Loc# 324472



Photo#2:
Silt fence is installed as perimeter control along south side of site.

April 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SG Interests Loc# 324472



Photo#3:
BMP installed at break midpoint in Silt Fence.

April 17, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SG Interests Loc# 324472