

Inspection Photos

API# 103-07565

Operator: Windsor Energy

Inspection Number: 680102879

Inspection Date: 4/12/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location Center to North.

April 12, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-07565



Photo#2:

There are areas which have sparse or are bare of, vegetation; pieces of Debris in foreground.

April 12, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-07565



Photo#3:
Debris & Gravel remain on site.

Photo#4:

April 12, 2018



Photo#5:

Access Road has not been reclaimed.

April 12, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-07565



Photo#6:
Culvert in Access road

April 12, 2018



Photo#7:
Debris on Access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA API# 103-07565