

# *Inspection Photos*

*Loc#311747*

*Operator: Laramie Energy*

*Inspection Number: 680102887*

*Inspection Date: 4/16/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Site is being inundated by Spring runoff waters which are eroding existing Pad Surface. and reclaimed areas.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#311747



Photo#2:

Site is being inundated by Spring runoff waters which are eroding existing Pad Surface. and reclaimed areas.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#311747





**Photo#3:**

Site is being inundated by Spring runoff waters which are eroding existing Pad Surface. and reclaimed areas.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#311747



**Photo#4:**  
Existing ditches are diverting some of runoff water.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Loc#311747