

Inspection Photos

Location Name: SLW State PC #BB18-65HN

Location ID: 426414



Photo 1: Location, looking NE



Photo 2: Wellheads, looking SE



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SLW State PC #BB18-65HN

Location ID: 426414



Photo 3: Stained soil at truck loadouts



Photo 4: Stained soil at wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SLW State PC #BB18-65HN

Location ID: 426414



Photo 5: Unmarked chemical pump



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources