



**Photo 1. View of the project area from the northeastern corner facing southwestward. Vegetation grazed and not in identifiable condition at this point in the growing season. Will need re-seeding and possible cattle exclusion if vegetation cover is not increasing in 2018.**



**Photo 2. View of the project area from the northeastern corner facing center.**



**Photo 3. View of electrical equipment near the center of the project area. This needs to be removed.**