

Worked on Thursday, 10/26/2017



**MARALEX RESOURCES  
INC**

P.O. Box 338  
Ignacio, CO 81137

P.O. Box 1979, Farmington, NM 87499  
(505) 325-2627

Name: South Shale Ridge 3-20  
API:05-077-08612, Rig #01

**Well Plugging Report**

**Cement Summary**

P #1 - P #1 M & P 12 sks 14.16 cf 15.8 ppg Class B Cmt. from 3093' to 2931' TOC. (BT #460)

**Work Detail**

Start	Stop	PUX	Activity
06:00 AM	07:30 AM	P	Travel to pump truck (SSR 10-15).
07:30 AM	08:30 AM	U	HSM on JSA. Issues starting pump truck change batteries.
08:30 AM	09:00 AM	P	Road equipment to loc.
09:00 AM	10:30 AM	P	Spot in equipment. LOBO rig PU 4.5" A Plus CR TIH. RU pump and cement equipment. Rig crew. CR premature set at 3093' release off CR LD 1 jnt sub up to CR pump and est. circ w/ 1 BBL pump 50 BBL clean up returns sting into CR attempt establish rate pressure up to 750 PSI NO RATE. W.O.O.
10:30 AM	12:00 PM	P	Gregorio R. w/ BLM ok'D spot cement 12 sks above CR and move on w/ procedure W/O looking for hole in csg. need not WOC and proced w/ procedure.
12:00 PM	12:30 PM	X	P #1 M & P 12 sks 14.16 cf 15.8 ppg Class B Cmt. from 3093' to 2931' TOC.
12:30 PM	01:30 PM	P	Drain pump and equipment secure equipment. Wait for RMWL to perf. P #2 in A.M. SDFD.

\* P - Procedure Planned; U - Unplanned A+ Issue; X - COA, Well Conditions

**Crew:**

Title	Name	Hours	Vehicle
Derrick:	Alcon, Joey	8.50	
Operator:	Sanchez, Oscar	8.50	
Supervisor:	Comanche, Dereck	8.50	60 - Crew PU

**On Site Reps:**

Name	Association	Notes
Gregorio Rios	BLM	On loc.
Jim Graves	Co. Rep.	W/ Maralex on. loc.

**Equipment:**

#645 lgr. - WASTE PITS

Worked on Saturday, 10/28/2017



**MARALEX RESOURCES  
INC**

P.O. Box 338  
Ignacio, CO 81137

P.O. Box 1979, Farmington, NM 87499  
(505) 326-2627

Name: South Shale Ridge 3-20  
API:05-077-08612, Rig #01

**Well Plugging Report**

**Cement Summary**

P #2 - M & P 35 sks 41.3 cf 15.6 PPG Class B Cmt from 1450' to 1248' TOC. w/ 20 out, 3 below, and 12 above.

P #3 - (Surface) M & P 110 sks 129.8 cf 15.6 PPG Class B Cmt. From 347' to 0' good cmt returns out BH valve. circ. 1.5 BBL cmt

**Work Detail**

Start	Stop	PUX	Activity
06:00 AM	12:00 PM	P	Travel back to head quarters
06:30 AM	08:00 AM	P	Travel to location
08:00 AM	10:30 AM	P	HSM on JSA service start equipment. RMWL tag P #1 at 2944', perf 4 holes at 1450'. Rig crew PU A Plus 4.5" CR TIH set CR at 1411' RU pump Establish injection rate of 1.5 bbl at 1000 PSI, circ. clean attempt PT csg no test.
10:30 AM	11:00 AM	P	P #2 M & P 35 sks 41.3 cf 15.6 PPG Class B Cmt from 1450' to 1248' TOC. w/ 20 out, 3 below, and 12 above.
11:00 AM	03:00 PM	X	Rig crew search for holes in csg found holes in csg at 347' BLM ok use holes circ. surface plug.
03:00 PM	04:00 PM	P	P #3 (Surface) M & P 110 sks 129.8 cf 15.6 PPG Class B Cmt. From 347' to 0' good cmt returns out BH valve. circ. 1.5 BBL cmt
04:00 PM	05:00 PM	P	RD/Drain Pump and cmt equipment. Road equipment to next loc. secure SDFD.
05:00 PM	06:00 PM	P	Travel back to Grand Junction.

\* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

**Crew:**

Title	Name	Hours	Vehicle
Derrick:	Alcon, Joey	6.00	
Derrick:	Alcon, Joey	11.50	
Operator:	Sanchez, Oscar	6.00	
Operator:	Sanchez, Oscar	11.50	
Supervisor:	Comanche, Dereck	6.00	60 - Crew PU
Supervisor:	Comanche, Dereck	11.50	60 - Crew PU

**On Site Reps:**

Name	Association	Notes
Gregorio Rios	BLM	On location