

Inspection Photos

07/19/2018

Operator: WALSH* FRANK H - 94100

Location ID: 405947

Inspection Doc. Number: 682503638

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WALSH* FRANK H - 94100
Location ID: 405947



Photo 1: Photo taken from the south end of the location. Photo shows riser equipment remaining.



Photo 2: Photo taken from the northwest end of the location. Photo shows riser equipment remaining.

Inspection Photos
Operator: WALSH* FRANK H - 94100
Location ID: 405947



Photo 3: Photo taken from the west end of the location, facing east. Photo shows bare areas where various asphalt debris remains.

Inspection Photos
Operator: WALSH* FRANK H - 94100
Location ID: 405947



Photo 3: Photo taken from the southwest corner of the location, facing north.



Photo 4: Photo taken from the north end of the location, facing east. Photo shows crop establishment in the interim area.