

Inspection Photos
Location Name: Judy 1-30
API: 05-057-06466



Photo 1. Overview of location taken at entrance facing east.

Inspection Photos
Location Name: Judy 1-30
API: 05-057-06466



Photo 2. No NFPA diamond on tank labels.



Photo 3. Stained soil.