

**Inspection Photo**  
**CSF 1-10W**  
**API # 045-06273**  
**Inspection # 689301729**



**Location Photo #1,**



**Location Photo #2**



**Inspection Photo  
CSF 1-10W  
API # 045-06273  
Inspection # 689301729**



**Location Photo #3,**



**Location Photo #4, holes in wire, standing oil in catch pan.**



**Inspection Photo  
CSF 1-10W  
API # 045-06273  
Inspection # 689301729**



**Location Photo #5, used oil in drip pan**



**Location Photo #6, oil on floor of unit.**

**Inspection Photo**  
**CSF 1-10W**  
**API # 045-06273**  
**Inspection # 689301729**



**Location Photo #7**

