

**Chevron TR 32-21-597**  
**API# 05-045-12269**  
**Inspection# 689701718**



**Location photo.**

**Chevron TR 32-21-597**  
**API# 05-045-12269**  
**Inspection# 689701718**



**Oily stains around wells.**



**Chevron TR 32-21-597**  
**API# 05-045-12269**  
**Inspection# 689701718**



**Junk at wells**



**Junk by tank battery.**

**Chevron TR 32-21-597**  
**API# 05-045-12269**  
**Inspection# 689701718**



**No labels on chemical containers.**