

Inspection Photos
Location Name:Haake Farms Inc GU#1
Location ID:319849



Photo#1 Production tank and Produced Water Pit



Photo#2 Separator/Gas Meter/ECD/Automation RTU

Inspection Photos
Location Name:Haake Farms Inc GU#1
Location ID:319849



Photo#3 Wellhead



Photo#4 Corrective Action-Unused equipment