

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2018

Submitted Date:

09/01/2018

Document Number:

680303846**FIELD INSPECTION FORM**Loc ID 337029 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	970-332-3585	gjones@ownresources.com	
Jones, Greg		gjones@augustusenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281780	WELL	PR	12/02/2005	GW	125-09712	CROSSLAND 44-35 5N46W	PR

**General Comment:**

Routine Inspection - SATISFACTORY

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track - grassland		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 281780	Type: WELL	API Number: 125-09712	Status: PR	Insp. Status: PR
Producing Well				
Comment:	GW			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT