

Inspection Photos

Loc#335857

Operator: Caerus

Inspection Number: 692400089

Inspection Date: 8/23/2018





Photo#1:
Overview of Location to Southwest.

August 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335857



Photo#2:

Present areas of Interim Reclamation are sparsely vegetated. Cut slope area populated with Cheat grass.

August 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335857



Photo#3:
If seeding of Fill slopes was attempted it has been unsuccessful.

August 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335857



Photo#4:

Steep Fill slopes are unstable, loose rocky material is not contained by apparent BMPs

August 23, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc#335857