

**Inspection Photo  
Savage RMV 101-28  
API # 045-07248  
Inspection # 689302015**



**Location Photo #1, uncontrolled weeds near wellhead.**

**Location Photo #2**

**Inspection Photo  
Savage RMV 101-28  
API # 045-07248  
Inspection # 689302015**



**Location Photo #3**



**Location Photo #4, uncontrolled weeds near separator.**

**Inspection Photo  
Savage RMV 101-28  
API # 045-07248  
Inspection # 689302015**



**Location Photo #5, non legible wellhead sign**



**Location Photo #6, non legible wellhead sign.**