

**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Dead weed debris at wells**



**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Tank battery**

**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Dead weed debris at tank battery**



**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Dead weed debris at separators**

**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Storm water from hill washing from corner to fence line of separators.**



**Inspection # 689701872**

**Storm water from hill washing from corner to fence line of separators.**

**GM 24-27**  
**Api# 045-07592**  
**Inspection # 689701872**



**Pooling of storm water at separators.**