



00244564

RECEIVED

OCT - 6 1997

COLO. OIL & GAS CONS. COM.

DOUBLE JACK TESTING & SERVICES, INC.
PHONE (307) 382-4020

B.O.P. TEST REPORT

B.O.P. TEST PERFORMED ON (DATE) 9-30-97
OIL COMPANY NIELSON AND ASSOCIATES
WELL NAME & NUMBER #1 FRENCH WOMAN
SECTION SW NE 15
TOWNSHIP 11N
RANGE 76W
COUNTY & STATE LARIMER, CO.
DRILLING CONTRACTOR HAYES #1
OIL COMPANY SITE REPRESENTATIVE ED MARTIN
RIG TOOL PUSHER _____
TESTED OUT OF ROCK SPRINGS
NOTIFIED PRIOR TO TEST _____
COPIES OF THIS TEST REPORT SENT TO: BLM LITTLE SNAKE R.A.
STATE OF CO.

ORIGINAL CHART & TEST REPORT ON FILE AT:

DOUBLE JACK TESTING & SERVICES, INC.
P. O. BOX 910
GREEN RIVER, WY 82935

TESTED BY:

John Blakeman

RECEIVED
ces Inc.
6 OCT - 6 1997

FIELD TICKET

OCT - 6 1997

Field Operations:

~~X~~ NIELSON + ASS. Operator
~~X~~ HAYES #1 Contractor
#1 FRENCH WOMAN Well Name

SW NE 15 11N 76W

Purchase Order # Ed M. [Signature]
Company Representative

Double Jack Blakeman
Double Jack Testing Representative

Subtotal	_____
Tax	_____
TOTAL	_____

f this account shall not be paid when due and it is placed with an attorney for collection, or if suit be instituted for collection, the undersigned agree(s) to pay in either case, reasonable expense of collection including attorney's fees and court cost in compliance with TRUTH IN LENDING AND THE UNIFORM CONSUMER CREDIT CODE, the following information disclosure, under the terms of our regular accounts, all amounts for service due and payable within THIRTY (30) DAYS from the receipt of an invoice for such services. A LATE CHARGE will be assessed when accounts are not paid when due. THE LATE CHARGE is computed by a "periodic rate" 1-3/4% PER MONTH which is an ANNUAL PERCENTAGE RATE OF 21% to the previous balance in the account on the billing date. No further credit can be extended on unpaid delinquent accounts until the delinquent account is paid in full. The contractor will not be held liable for damages caused by acts of God, or unforeseen circumstances that could not be reasonably anticipated in performing the work done as set forth above.

[illegible]


3 1/2 pipe
rams

Blind
rams

③

②

③



change
over
spool

①

①

①

①

2000 psi
well head

