

# Inspection Photos

10/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 318182

Inspection Doc. Number: 682504016

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo from the southwest end of the former battery location, facing northeast. Photo shows large areas of the battery location remains bare and exposed soil. Photo also shows Echinochloa crus-galli (Barnyardgrass) appears to have been planted at the battery and well location. This is an annual grass that can be weedy according to the USDA, reference area is perennial cropland; vegetation is not reflective of the reference area.



**Photo 2:** Photo from the east end of the former battery location, facing west. See comments under photo 1.





**Photo 3:** Photo taken from the battery location. Photo shows inspector conducted a compaction test; inspector was only able to easily penetrate the top couple inches of the soil on the location. Compaction concerns remain evident.



**Photo 4:** Photo taken from the adjacent reference area. Photo shows inspector was able to easily penetrate the top 6-8 inches of soil on the reference area.