

**Inspection Photo
Couey 17-12C
API # 045-13466
Inspection # 689302200**



Location Photo #1



Location Photo #2, Frac sand near wellheads.

**Inspection Photo
Couey 17-12C
API # 045-13466
Inspection # 689302200**



Location Photo #3, frac sand near wellheads

Location Photo #4, Fracsand near wellheads

**Inspection Photo
Couey 17-12C
API # 045-13466
Inspection # 689302200**



Location Photo #5, sediment being moved off location



Location Photo #6, Rock check dams washed out

**Inspection Photo
Couey 17-12C
API # 045-13466
Inspection # 689302200**



Location Photo #7, Sediment being moved off location

Location Photo #8, Failed rock check dams

**Inspection Photo
Couey 17-12C
API # 045-13466
Inspection # 689302200**



Location Photo #9, Sediment being moved off location and down hill into open area below

