

Inspection Photos

Location Name: 05-103-08442 (GOVERNMENT 398-17-4)

Location ID: 315399

Inspection: 679701518



location



Cow inside separator fencing.

Inspection Photos

Location Name: 05-103-08442 (GOVERNMENT 398-17-4)

Location ID: 315399

Inspection: 679701518



Separator fence unsecured



Methanol label



Inspection Photos

Location Name: 05-103-08442 (GOVERNMENT 398-17-4)

Location ID: 315399

Inspection: 679701518



Missing 100 on capacity



Missing 300 on capacity



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 05-103-08442 (GOVERNMENT 398-17-4)

Location ID: 315399

Inspection: 679701518



Dead bird in Methanol secondary containment



Hole in mesh in Methanol secondary containment. Birds can fly in, but can't fly back out.