

Inspection Photos
Location Name: B & V Pad
Location: 440634



Location at the Entry



Location Sign

Inspection Photos
Location Name: B & V Pad
Location: 440634



Holes at edge of location



Hazard not marked or covered on location.

Inspection Photos
Location Name: B & V Pad
Location: 440634



Weeds not maintained in the Storm Water BMP



Weeds on Berms around location.

Inspection Photos
Location Name: B & V Pad
Location: 440634



Sediment movement past BMP



Debris incorporated into the un stabilized berm

Inspection Photos
Location Name: B & V Pad
Location: 440634



BMP not maintained and sediment movement



Berm not stabilized with signs of erosion.

Inspection Photos
Location Name: B & V Pad
Location: 440634



Pipe line Route on CR 301 Parachute , CO



Inspection Photos
Location Name: B & V Pad
Location: 440634



39.27'05.34 N 108.02'32.78 W



Entry to pipe line available to Wildlife



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: B & V Pad
Location: 440634



North of the Colorado River



Entry point onto CR 301

Inspection Photos
Location Name: B & V Pad
Location: 440634



Poly pipe crossing Colorado River on CR 301. Walk Way installed over Poly pipe.



Pipe leaving CR 301 Bridge to cross under bridge and re route to the east side of CR 301

Inspection Photos
Location Name: B & V Pad
Location: 440634



Valve on east side of CR 301



Jersey Wall along the Right of Way on CR 301

Inspection Photos
Location Name: B & V Pad
Location: 440634



Line on east side of CR 301



Sign along CR 301

Inspection Photos
Location Name: B & V Pad
Location: 440634



Line on east side of CR 301



39.27'18.36 N 108.02'05.33 W