

# *Inspection Photos*

*ALs @Loc#335960*

*Operator: Caerus/ Marathon*

*Inspection Number: 692400290*

*Inspection Date: 10/19/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View of Plate covering Casing; following photo shows uncovered.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus/Marathon ALS Loc#335960





Photo#2:

Plate removed from casing.

October 19, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus/Marathon ALS Loc#335960