

Inspection Photos

Loc#335960

Operator: Caerus

Inspection Number: 692400300

Inspection Date: 10/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from lease road to Northeast.

October 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus/Marathon ALS Loc#335960



Photo#2:

View from Southeast side of site to cut slope at Northwest corner of Location.

October 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus/Marathon ALs Loc#335960



Photo#3:

View of sparsely vegetated South fill slope.

October 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus/Marathon ALs Loc#335960