

ALANCO ENERGY SERVICES INC - 10493
API# 05-077-10096 Deer Creek SWD #1
Inspection Date : 11/2/2018



Wellhead with no sign. No fencing.

Trash & debris around wellhead.

4' cellar with mesh grate. 10.75" & 7" casings exposed above grate.

Cellar full of water. No visible cement in annulus.

No valves on casing. 7" casing plug is open ended.



**Overview of wellhead area looking NW with
CDPHE permitted waste water facility equipment
and evap pits in background**

ALANCO ENERGY SERVICES INC - 10493
API# 05-077-10096 Deer Creek SWD #1
Inspection Date : 11/2/2018



**Overview of water disposal facility looking SW.
2-400 bbl and 1-500 bbl tanks. Access hatches removed.
3-400 bbl tanks with cement bermed offload pad.**



**SW corner looking N of cement bermed offload pad.
3-400 bbl tanks with access hatches removed.**