

Location Name: B & V



Debris along berm has been removed. Straw bales have been re-installed as needed. Holes behind separators have been filled in. Weed debris has been cleared from diversion ditch and berm.