

Inspection Photos

Loc#335477

Operator: Dolphin Energy

Inspection Number: 692400334

Inspection Date: 10/26/2018





Photo#1:
Overview of Reclaimed Cut slope area at East side of Location.

October 26, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Arroyo Loc#335477



Photo#2:

Close up of area that was hand seeded in Spring 2018. Vegetation is predominately Cheat grass.

October 26, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Arroyo Loc#335477



Photo#3:

Close up of area that was hand seeded in Spring 2018. Vegetation is predominately Cheat grass.

October 26, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Arroyo Loc#335477