

Inspection Photos

Location Name: Phoenix Resources (Ramsey Property)

Holt #1

API: 05-009-06676




1. Lease sign

2. Tank battery with inadequate berms



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Phoenix Resources (Ramsey Property)
Holt #1
API: 05-009-06676



3. Treater



4. Wellhead equipment

Inspection Photos

Location Name: Phoenix Resources (Ramsey Property)

Holt #1

API: 05-009-06676



5. Wellhead, after clean up



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources