

Inspection Photos

11/14/2018

Operator: DENVER EAST MACHINERY COMPANY
- 24040

Location ID: 374981

Inspection Doc. Number: 682504140
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the area of the former battery/pit. Photo shows pipe debris remaining on site.



Photo 2: Photo taken from the area of the former battery/pit. Photo shows pipe debris remaining on site.



Photo 3: Photo taken from the area of the former battery/pit. Photo shows concrete debris remaining on site.



Photo 4: Photo taken from the area of the former battery/pit, facing east. Photo shows area of salt kill down gradient of the pit. Photo shows salt kill remains evident and crop remains unable to establish within these areas.



Photo 5: Photo taken from the area of the former battery/pit, facing north. Photo shows area of salt kill down gradient of the pit. Photo shows salt kill remains evident and crop remains unable to establish within these areas.



Photo 6: Photo taken from the salt kill, facing west. Photo shows salt kill remains evident and crop remains unable to establish within these areas.



Photo 7: Photo taken from the salt kill, facing east. Photo shows erosion degradation remains evident.



Photo 8: Photo taken from the salt kill, facing west. Photo shows erosion degradation remains evident. 6 foot measuring stick for reference.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 9: 1998 aerial imagery. Photo shows battery and pit location. Pit in red. Photo also shows a large bare area directly to the east of the well. Bare area likely a salt kill.



Photo 10: 2016 aerial imagery. Photo shows battery and pit location. Pit in red. Photo also shows a large bare area directly to the east of the well. Bare area likely a salt kill. Main bare area seen in yellow ~1 ac in size.