

Inspection Photos
Location Name: Bader Collins #1
Location ID: 307139



Production facility



Produced water tank placarding

Inspection Photos
Location Name: Bader Collins #1
Location ID: 307139



Trash



Trash

Inspection Photos
Location Name: Bader Collins #1
Location ID: 307139



Trash



Weeds

Inspection Photos
Location Name: Bader Collins #1
Location ID: 307139



Weeds



Weeds

Inspection Photos
Location Name: Bader Collins #1
Location ID: 307139



Wellhead sign