

**Inspection Photos**  
**Location Name: WEAVER RIDGE 23-16**  
**Location ID: 05-103-10520**  
**Inspection: 679702461**



**Photo 1. Location looking north.**




**Photo 2. Separator and gas meter building.**

**Inspection Photos**  
**Location Name: WEAVER RIDGE 23-16**  
**Location ID: 05-103-10520**  
**Inspection: 679702461**



**Photo 3. Tank battery.**



**Photo 4. Well head.**

Inspection Photos  
Location Name: WEAVER RIDGE 23-16  
Location ID: 05-103-10520  
Inspection: 679702461



Photo 5. Tank without capacity volume.