

Inspection Photos

1/10/2019

Operator: PCR OPERATING LLC - 10657

Location ID: 313784

Inspection Doc. Number: 682504407

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northwest corner of the location, facing southeast. Photo shows large areas of the location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation has been conducted.



Photo 2: Photo taken from the north end of the location, facing south. See comments under photo 1. Vegetation seen in photo Russian thistle.



Photo 3: Photo taken from the east end of the location, facing west. See comments under photo 1. Vegetation seen in photo Russian thistle.



Photo 4: Photo taken from the south end of the location, facing northeast. See comments under photo 1. Vegetation seen in photo Russian thistle.

Inspection Photos
Operator: PCR OPERATING LLC - 10657
Location ID: 313784



Photo 5: Photo taken from the south end of the location, facing northwest. See comments under photo 1. Vegetation seen in photo Russian thistle.



Photo 6: Photo taken from the north end of the location, facing north. Photo shows access road has not been reclaimed; access road remains predominantly bare and exposed soil



Photo 7: Photo taken from the access road entrance. Photo shows cattle guard has not been removed or access road reclaimed. Photo also shows a fence panel has been placed across cattle guard.



Photo 8: Photo taken from the access road entrance. Photo shows cattle guard has not been removed or access road reclaimed. Photo also shows a fence panel has been placed across cattle guard.



Photo 9: Photo taken from the adjacent reference area. Photo shows vegetation over reference. Vegetation observed predominantly Sand dropseed, blue grama, western wheatgrass, sand sage, etc...