

SGU CP11D-34 M34
Api # 05-045-14534
Inspection # 689702501



Location photo

SGU CP11D-34 M34
Api # 05-045-14534
Inspection # 689702501



No surface indication of 2" riser.
Unused equipment has been removed from location.