

Inspection Photos  
Location Name: Hosmer #4-4  
Location ID: 319871



**Photo 1 TNK BTRY WEEDS**



**Photo 2 PU WEEDS**

**Inspection Photos**  
**Location Name: Hosmer #4-4**  
**Location ID: 319871**



**Photo 3 stained soil load line VLV on back of west crude oil tank**



**Photo 4 Stained soil on west crude oil tank**

**Inspection Photos**  
**Location Name: Hosmer #4-4**  
**Location ID: 319871**



**Photo 5 TNK BTRY WEEDS**

**Photo 6 Stained soil PU MOTOR**

**Inspection Photos**  
**Location Name: Hosmer #4-4**  
**Location ID: 319871**



Colorado Oil and Gas Conservation Commission  
39.91133, -104.56233, 1584.9m  
Jan 29, 2019 12:47:26 PM

**Photo 7 stained soil around PU motor**



Colorado Oil and Gas Conservation Commission  
39.91119, -104.56229, 1584.9m  
Jan 29, 2019 12:47:43 PM

**Photo 8 Weeds around SEP**

**Inspection Photos**  
**Location Name: Hosmer #4-4**  
**Location ID: 319871**



**Photo 9 production tank weeds and not adequate birms**

**Photo 10 ECD VLV closed**

**Inspection Photos**  
**Location Name: Hosmer #4-4**  
**Location ID: 319871**



**Photo 11 Sales line LOTO**



**Photo 12 LOC PIC**